


**IEPA - DIVISION OF WATER POLLUTION CONTROL
DIGITAL PHOTO REPORT**

Date: 5-23-13	Site Name: James McCune
Photo By: Lee Heeren	
County: Bureau	
Comments: A view of the M-6 swine facility located southeast of the <small>Exemption 6 and Exemption 7(C)</small> address for James McCune on 1945 N Avenue. This 3600-hog capacity building has 8 ft deep manure pits and tunnel ventilation. View is southeast.	
Photo #: 1	
Photo Title: 052313_JamesMcCune_LH(1)	

Date: 5-23-13	Site Name: James McCune
Photo By: Lee Heeren	
County: Bureau	
Comments: A view of the M-5 swine facility located adjacent west of the <small>Exemption 6 and Exemption 7(C)</small> This is a 3600-hog capacity barn that contains an 8 ft manure pit and tunnel ventilation. View is northwest.	
Photo#: 2	
Photo Title: 052313_JamesMcCune_LH(2)	

Initials: svf

**IEPA - DIVISION OF WATER POLLUTION CONTROL
DIGITAL PHOTO REPORT**


Date: 5-23-13	Site Name: James McCune
Photo By: Lee Heeren	
County: Bureau	
Comments: A view of the M-1 swine facility located approx. [redacted] on 1945 N Avenue. There are three 1100-hog capacity barns having a 2 ft partial manure pit that contains a scraper system that transfers the manure into a reception pit and ultimately into an adjacent 1.6 MG Slurrystore. These barns are older, naturally ventilated barns. View is northwest.	
Photo #: 3	
Photo Title: 052313_JamesMcCune_LH(3)	

Date: 5-23-13	Site Name: James McCune
Photo By: Lee Heeren	
County: Bureau	
Comments: A view of an earthen feedlot for some of the beef cows and calves. View is northwest.	
Photo #: 4	
Photo Title: 052313_JamesMcCune_LH(4)	

Initials: svf

**IEPA - DIVISION OF WATER POLLUTION CONTROL
DIGITAL PHOTO REPORT**

Date: 5-23-13	Site Name: James McCune
Photo By: Lee Heeren	
County: Bureau	
Comments: Another view of the feedlot. The M-1 swine buildings are shown in this photo. View is northwest.	
Photo #: 5	
Photo Title: 052313_JamesMcCune_LH(5)	

Date: 5-23-13	Site Name: James McCune
Photo By: Lee Heeren	
County: Bureau	
Comments: A view of the Exemption 6 and E swine facility containing three 1200-hog capacity buildings with 8 ft manure pits and natural ventilation. They are located in Section 32 of Fairfield Township, Bureau County. View is northwest.	
Photo#: 6	
Photo Title: 052313_JamesMcCune_LH(7)	

Initials: svf


**IEPA - DIVISION OF WATER POLLUTION CONTROL
DIGITAL PHOTO REPORT**

Date: 5-23-13	Site Name: James McCune
Photo By: Lee Heeren	 A photograph showing four large, cylindrical metal grain silos standing on a gravel lot. In the background, there is a long, low barn with several cupolas. The sky is overcast.
County: Bureau	
Comments: A view of the Anderson South swine facility located at 22795 Ill. Rt. 40, Sheffield, IL. It is located in Section 9 of Manlius Township, Bureau County. The facility comprises of three 1100-pig capacity, naturally ventilated barns with 2 ft partial manure pits and scraper system that empties into a 1.6 MG Slurrystore. View is southwest.	
Photo #: 7	
Photo Title: 052313_JamesMcCune_LH(9)	

Date: 5-23-13	Site Name: James McCune
Photo By: Lee Heeren	 A photograph of a large, dark blue cylindrical slurry store. A piece of heavy machinery, a "spider" agitation unit, is positioned in front of it. The unit has a long, articulated arm extending over the top of the slurry store. The foreground is a gravel area, and there is some green grass to the left. The sky is cloudy.
County: Bureau	
Comments: A view of the 1.6 MG Slurrystore and a Balzer "spider" agitation unit that goes over top of the Slurrystore to stir the hog manure during the emptying procedure. This unit is more aggressive than the equipment on the Slurrystore. View is southwest.	
Photo#: 8	
Photo Title: 052313_JamesMcCune_LH(8)	

Initials: svf


**IEPA - DIVISION OF WATER POLLUTION CONTROL
DIGITAL PHOTO REPORT**

Date: 5-23-13	Site Name: James McCune
Photo By: Lee Heeren	
County: Bureau	
Comments: A view of the south swine facility containing three 1100-pig capacity, naturally ventilated, shallow manure pit barns. A scraper system transfers the manure into a reception pit and into a 1.6 MG Slurrystore. An identical set of buildings are located north of these that belong to [REDACTED] These buildings are located in Section 34 of Manlius Township, Bureau County along Ill. Rt. 40. Notice the border trees designed to camouflage the swine facilities. View is northeast.	
Photo #: 9	
Photo Title: 052313_JamesMcCune_LH(11)	

Date: 5-23-13	Site Name: James McCune
Photo By: Lee Heeren	
County: Bureau	
Comments: A view of the Boar Power facility located at 450 East Ave., Sheffield. It is in Section 23 of Gold Township, Bureau County. This barn has a 2400-pig capacity with a 10 ft manure pit and natural ventilation. Two older barns are located on this site that are due to be demolished. Another 2400 capacity barn is anticipated at this site. View is southwest.	
Photo#: 10	
Photo Title: 052313_JamesMcCune_LH(15)	

Initials: svf

**IEPA - DIVISION OF WATER POLLUTION CONTROL
DIGITAL PHOTO REPORT**

Date: 5-23-13	Site Name: James McCune
Photo By: Lee Heeren	
County: Bureau	
Comments: A blurry view of the Boar Power site from the south that shows the two older buildings that are due to be replaced. View is northwest.	
Photo #: 11	
Photo Title: 052313_JamesMcCune_LH(12)	

Date: 5-23-13	Site Name: James McCune
Photo By: Lee Heeren	
County: Bureau	
Comments: A view of the two 7500 gal. Balzer tank wagons/injectors and a Knight slinger wagon used for the semi-solid cattle manure.	
Photo#: 12	
Photo Title: 052313_JamesMcCune_LH(14)	

Initials: svf

**IEPA - DIVISION OF WATER POLLUTION CONTROL
DIGITAL PHOTO REPORT**

Date: 5-23-13	Site Name: James McCune
Photo By: Lee Heeren	
County: Bureau	
Comments: A view of the lined manure basin that is used for the truck wash operation. The truck wash is a commercial business and has a NPDES Operating Permit. The structure will be emptied on harvested wheat acreage in June. View is northeast.	
Photo#: 13 Photo Title: 052313_JamesMcCune_LH(13)	

Initials: svf